

Overview

Unico 4000 Series Controllers based on the Motorola 68000 CPU have entered a “repair only / no new boards available / replacement suggested” status due to obsolescence of the 68000 and associated support chips. The controllers suggested for replacement have “68000” on the faceplate similar to that shown in the photo.

The 68360 based controller fits into the same slot requiring minimal changes to the hardware. Software updates and re-commissioning can be accomplished with minimal downtime.

It is suggested that users contact Rick Johnson – Unico Aftermarket phone support @ 262.504.7223 or your regional Unico Sales office for details and to schedule a controller upgrade.



UPGRADES/ RETROFITS

Obsolescence /
Replacement Notification
68000 CPU

UNICO-Worldwide



Corporate Headquarters

Unico, Inc.
3725 Nicholson Rd.
P. O. Box 0505
Franksville, WI
53126-0505
262.886.5678
262.504.7396 fax
www.unicous.com



Unico is a leading global innovator of motion-control solutions for industry. Founded in 1967, the company develops, manufactures, and services variable-speed drives, application-engineered drive products, integrated drive systems, and ancillary products that improve operations by increasing productivity, safety, and equipment life while lowering energy and maintenance costs.



All trade designations are provided without reference to the rights of their respective owners.

Specifications subject to change without notice.